

Grey O. Nina President & CEO

1738 Crotona Park East, Suite 3A Bronx, NY 10460 Tel: (646) 600-0558 Fax: (718) 228-3627 greyonina@gandjlc.com www.GandJLC.com

 $\star$ 



New York State Certified

## CERTIFICATIONS

New York State Office of General Services Metropolitan Transportation Authority New York City Small Business Services

SDVOSB 6/28/2020 DBE 2/11/2020 MBE/WBE

New York State SAM.gov

MBE/WBE 3/1/2019 **EDWOSB** 

 $\star$ 

 $\star$ 

## 236220 - CONSTRUCTION

· Construction (including new

- All other Specialty Trade Contractors
- work, additions, alterations, maintenance, and repairs) of commercial and institutional buildings and related structures and indoor swimming facilities.
- Concrete Work (Polishing) Shot Blasting
- · On-site assembly of modular or prefabricated commercial and institutional buildings

### 238320 - PAINTING AND WALL COVERING

- Sand Blasting
- · Coating application
- Damp proofing
- · Concrete & brick restoration

#### 562910 - REMEDIATION

- · Lead Paint Abatement
- Mold Remediation
- ACM Repair & Maintenance
- Soil Remediation
- · PCB & Mercury Removal

· Above and below ground

waterproofing services

Pressure washing

· Stripping / Seal Coat

- Gun Range Clean-Up
- Water Damage Restoration
- · Bird Guano Remediation
- Pipe Re-Insulation
- · Re-Spray Fireproofing
- HVAC Duct Cleaning

#### NAICS CODE:

- 238990 All Other Specialty Trade Contractors
- 238320 Painting and Wall Covering Contractors
- Electrical Contractors and Other Wiring Installation 238210
- 238190 Other Foundation, Structure, & Building Exterior Contractors
- Masonry Contractors 238140
- 238120 Structural steel and Precast concrete contractors
- 236220 Commercial and Institutional Building Construction
- Industrial Building Construction 236210

# **PERFORMANCE:**

 Dormitory Authority of the State of New York DASNY Baruch College / XBR Inc.

 $\star$ 

- Atlantic Aviation 6N5:
  - Construction and interior renovation of office space
  - Interior demolition of wall (Fuel Station)
  - Carpet removal and installation
- Kevco Construction Services Fabrina Construction Corp Corp. Painting of multiple residential apartments - NYC
- DDC/ XBR Inc.: South Shore Little League SOW - Furnish & Install Aluminum Bleachers/Stairs, Doors & Hardware, miscellaneous metal, welding, and carpentry.
- DDC/ XBR Inc.: Dancewave Inc.,

SOW consisted of demolition, framing, Gypsum board installation, firestopping, ceiling, taping, and painting.

• Chappaque Crossing Apts: P

Scope of work consist of power washing, interior and exterior painting, windows restoration, molding and trim installation.

• Rebuilding Together NYC

Scope - Renovation of residential homes in various locations.

- · GSA SOW consisted of repairs & painting of 290 Broadway 30th FI
- DASNY/XBR Baruch College: Scope consisted of taping, painting, drop ceiling installation and carpentry.
- NYCHA /Procida-Butz c/o Procida Construction Corp.
- NYCHA RAD BUNDLE III Hope & Bushwick Gardens
- DDC / XBR INC.- Steinway Library Phase II Renovation Carpentry Work •
- MTA / 10 November LLC / Contract A-37281 Stair repair at 79th St. and Broadway, Subway Station - Supply

### **COMPLETED PROJECTS:**

- DASNY / IANNELLI CONSTRUCTION Co., INC / YORK COLLEGE Escalator Enclosure (Carpentry Work - Painting) - 03/15/2019
- DASNY / IANNELLI CONSTRUCTION Co., INC / HUNTER COLLGE Carpentry Work - 09/09/2019

#### OSHA Fall Protection Site Safety

DUNS: 079191265

CAGE CODE: 70HG2

General Liability: \$2 Mil